• Work Order ID 60725 - 7

Wednesday, July 21, 2010 11:49:20 AM



Page 1

Item ID:

41232-000-001-001

Accept

Setup Start

Stop



Revision ID:

Item Name:

Required Date: 7/29/2010

Emergency Flotation Step Actuator, LH

Start Date:

7/21/2010

Start Oty: 2\00

Reg'd Oty: 2.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

MF

Date: 10-7-21 Tooling:

Date:

Run

Start

OC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/ Work Center ID

Operation Description

Set Un/ Run Hours Tool ID

Tool# Plan

Code

Accept Oty

Reject Oty

Reject Insp. Number Stamp

Draw Nbr

Revision Nbr

41232-000-001

Rev A

100

DOCUMENT CONTROL

Memo

0.00

0.00

Document Control

Photocopy bluefile D412-763 & type labels per PPP 41232-000-001 CHG 002

110

Pick Kit

0.00

Packaging Packaging

Memo

0.00

10/8/4 (2)

120

QC4-100% Inspect kits for completeness

0.00

Memo

0.00

Sidoshiz

Quality Control

Work Order ID 60725

Wednesday, July 21, 2010 11:49:20 AM

Item ID:

41232-000-001-001

Accept



Setup Start

Stop



Revision ID: Item Name:

Emergency Flotation Step Actuator, LH

Start Date:

7/21/2010

Start Qty: 2.00

Req'd Qty: 2.00



Cust Item ID:

Customer:

Tool ID

Reference:

Approvals:

Process Plan:

QC:

Date: Date: Tooling:

SPC (Y/N):

Date:

Date:

Tool#

Plan

Code

Start Run

Reject

Oty

Stop

Reject



Accept

Qty

Number Stamp

Insp.

Sequence ID/

Packaging

Packaging

Work Center ID

Required Date: 7/29/2010

Operation Description

Set Up/ Run Hours

0.00

Packaging

Memo

Identify and pack for shipping as per PPP 41232-000-001-001

Location:

PPP Rev:

0.00

140

130

QC21- Final Inspection - Work Order Release

0.00

Quality Control

Memo

0.00

10/08/13 Af

Picklist Print

Wednesday, July 21, 2010 11:49:19 AM

Work Order ID: 60725

Parent Item:

41232-000-001-001

Parent Item Name: Emergency Flotation Step Actuator, LH



Start Date: 7/21/2010

Required Date: 7/29/2010

Start Qty: 2.00

Required Qty: 2.00

Comments:

IPP Rev:A New Issue 07-02-28 JLM

IPP Rev:B

10.06.11 41232-200-006-001 replace with D4004.1 DD

	10.06.11 41232-20	0-006-001 replace	with D	14094-1 DD 1	verf:EC								
. Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit		Qty Issued	Date Issued	Status
SpHose ass'y-Step Actuator		Purchased	No			110	Each	8.0000		2		1	
41232-200-001-001 Step Actuator LH Ass'y 41232-200-003-001 Spring (Step Actuator)		Manufactured Manufactured	No No	Location ST389	110145	110	8 8 8 Each / C	Loc Code 0.00000		110145 2 598	BL	1018	le
41232-290-004-001 Reducer Tee Assembly		Manufactured	No	Location ST364	54173 52637		101 101 Each	1.0000 Loc Code		52 63) 10		Co

B5981P 10/8/125f

Picklist Print

· Wednesday, July 21, 2010 11:49:19 AM

Work Order ID: 60725

Parent Item:

41232-000-001-001

Parent Item Name: Emergency Flotation Step Actuator. LH

NAS1149D0463J Purchased

Purchased

No

No.

No

Start Date: 7/21/2010

Required Date: 7/29/2010

Start Qty: 2.00

Required Qty: 2.00

22.0000

Si	41232-200-005-001 Spacer (Step Actuator)	Manufactured
12	Spacer (Step Actuator)	

AN4-23A

AN960JD416

AP0925ELBN

Purchased No

Location Loc Qty Loc Code ST365 22 52636 2 59811 20 110 Each 79.0000

110

Each

Each

Location Loc Qty Loc Code ST359 79

107378 79 110 0.0000 Each

110

279.0000

NAS1149D0416J Purchased AN960JD416L No

Location Loc Qty Loc Code ST346 279 110153 279 110 Each 8.0000

Location Loc Qty Loc Code ST283 103727

14372

- Picklist Print

Wednesday, July 21, 2010 11:49:19 AM

Work Order ID: 60725

Parent Item:

41232-000-001-001

Parent Item Name: Emergency Flotation Step Actuator, LH



Start Date: 7/21/2010

Start Qty: 2.00

Required Date: 7/29/2010

Required Oty: 2.00

	D4094-1								
)	17111111111111	IIII	IIII		Ш	Ш		Ш	
17	Bracket	Ш	Ш	Ш	Ш		Ш	Ш	
l -	Bracket								

Manufactured No 110

Each 5.0000

	MS20392-3C21	P
4		
VI	2 11 11 11 11 11 11 11 11 11 11 11 11 11	
	D:	

urchased

No

No

Loc Qty 58263 110

5 Each

15,0000

Loc Code

58263

MS21042L4	
S	
12 Nut	

Purchased No

Purchased

ST315 104156

Location

Location

ST

15 15 Each 110

Loc Qty

3,929.000

Loc Code

SA	MS210 Nut				
1.0	Nut				

Location	Lo	c Qtv	Loc Code
ST300		3929	
113422		68	
114523		28	
114718		23	
114784		1810	
115108		2000	
	110	Each	634.0000

60	MS24665-151
7	Cotter Pin

Location	Loc Qty	Loc Code
ST309	634	
17566	634	

P.14446

Wednesday, July 21, 2010 11:49:19 AM

Work Order ID: 60725

Parent Item:

41232-000-001-001

Parent Item Name: Emergency Flotation Step Actuator, LH

Start Date: 7/21/2010

Required Date: 7/29/2010

Start Qty: 2.00

Required Qty: 2.00

Purchased

MS35489-93 - PEROMME

No

110

Each

80.0000

AMERICA STOLED cut 2x 18" long

Purchased

No

114341

Location

ST293

80 110

Loc Qty

61.4500

Loc Code

3.05

Location Loc Qty Loc Code ST389 61.45 104229 11.45 109886 50